

Basic Vehicle Condition Guide

Report ID: 18,331,235

Version:

Created: 17 Aug 2018

Make: Nissan Model: Note Body Style: Hatchback


 Year:
 2,013
 Registration:
 Reg Expiry:

 WoF Expiry:
 16 Aug 2019
 Odometer:
 87,432 Kms
 Good No:
 18331235

 VIN:
 7AT0DH79X18111030
 Next Service:
 97,400
 Service History:
 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Mathew Varghese Date: 16 Aug 2018

Name:

	Pass	Fail	N/A	
Engine	•	•		
Oil level	~			
Smoke & fumes	v			
Performance	~			
Noise	~			
Cooling System	•			
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	3	.0	mm	
Right front	3	.0	mm	
Left rear	3	.0	mm	
Right rear	3.0		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	V V V V V V			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera	~			

Signature: