

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Cooling System Coolant condition V V Performance S Key: Radiator / Hoses (visual) V S = scratch Transmission D = dent ς SC Operation V R = rustNoise V PT = paint defect C = crackClutch V P = pin dent CV joints ~ SC * = decals Wheel bearings V SC = stone chips Brakes W = significant scuffs P Performance ~ Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front mm 5.0 **Right front** mm 5.0 Left rear 4.0 mm **Right rear** mm Conditions During Body Inspection: 5.0 Wet Spare Yes Under Carriage & Under Bonnet Inspection Comments Suspension All good Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater V Operation Interior Comments Electrical / Accessories Good Head lights Seats 1 Tail lights 1 Good Carpets Indicators ~ Good Dashboard warning lights 1 Panels Wipers (front & rear) 1 Good Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Radio locked out. Window winder RR V V Rear view mirrors Radio (basic test only) ~ CD (basic test only) V Number of keys 1 V Central locking **Road Conditions During Test Drive:** Wet Remote locking V **Engine Timing Mechanism:** Cambelt Sat. Nav. (basic test only) V Evidence of Cam Belt Replacement: Kms: Yes 105,000 Reversing camera ~

Inspected by: Jacob

I have read and understood this condition guide.

20 Aug 2018 Date:

Name:

Signature:

Report ID: 56,206 Version: 3 Created: 20 Aug 2018

Pass

~

V

V

~

Fail

N/A

| ondition Guide | |
|----------------|--|
| | |

Engine

Oil level

Noise

Smoke & fumes

Performance