

Report ID: 18,331,804 Version: 1 10 Sep 2018 Created:

Make:	Nissan	Model:	Fuga	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,005	<b>Registration:</b>		<b>Reg Expiry:</b>		Engine	•		
WoF Expiry:	15 Aug 2019	Odometer:	46,381 Kms	Good No:	18331804	Oil level	~		
VIN:	7AT0DH8GX18210107	Next Service:	56400	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
					Р	Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	s dia			715	HIV	Operation	~		
PT = paint defe				$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				7414	CV joints	~		
* = decals	- All			- NG		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
D L		Note: som	ne defects & blemishes	may not be disc	blayed in the diagram	Hand Brake	~		
Body Insp	pection Comments			, ,	, ,	Tyres (lowest observed tread	-	of tyre	s)
					Left front 7 mm				
						Right front			 mm
						Left rear		7	mm
Canalitian	Dunin n De du la su		_			Right rear			 mm
Conditions During Body Inspection: Dry									
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
		•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		I
Interior Comments						Operation 🖌			
Good						Head lights			
Seats							<ul> <li></li> <li></li> </ul>		
Carpets	Good					Tail lights Indicators	<b>v</b>		
	Good						~		
Panels						Dashboard warning lights	<b>v</b>		
Dashboa	rd Good					Wipers (front & rear) Window winder FL	~		
							~		
General (	Comments					Window winder FR	~		
	<u>connents</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
	-					Number of keys	2		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
Engine Ti	ming Mechanism	Timina				Remote locking	~		<b> </b>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence		ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: John Lindsay Date: 10 Sep 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....