

Report ID: 18,331,917 Version: 1 18 Sep 2018 Created:

Signature:

Make:	Toyota	Model:	Caldina	Body Style:	SUV		Pass	Fail	N/A
Year:	2003	Registration:	FZF101	Reg Expiry:	12 Aug 2019	Engine			
WoF Expiry:	2003 24 Aug 2019	Odometer:	195,560 Kms	Good No:	12 Aug 2019 18331917	Oil level	~		
VIN:	7AT0H624X10012325	Next Service:	204973	Service Histor		Smoke & fumes	~		
	7,4101102-4,410012323		204975		110	Performance	~		
	port is not a warranty		<i>.</i>			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:	s sc s	-0	S SC S D SC		S SC	Radiator / Hoses (visual)	~		
S = scratch	STO	A CO			T	Transmission	v		
D = dent	s sc			The	S D SC	Operation	~		
R = rust				10	JHIK	Noise	~		
PT = paint def C = crack	ect M			+		Clutch			~
P = pin dent	Ho	KI			JIII —	CV joints	~		V
* = decals	sc PK			AL-	ELIP S	Wheel bearings			
SC = stone chi	ps U	VA		JAL)	& <u> </u>	Brakes	~		
W = significant scuffs PT SC S S P S P S SC						Performance			
		Noto: con	ne defects & blemishes			Hand Brake	~		
Body Inst	pection Comments	Note. son	le délects & blemisnes	illay not be disp	layed in the diagram			- f h m	
						Tyres (lowest observed tread depth of tyres)			
						Left front	7		mm
						Right front	7		mm
						Left rear	7 mm		
Conditions During Body Inspection: Dry						Right rear	7 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	inage & onder boi	met inspectio	<u>on comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation			~
drivers seat ripped worp, wear and tear						Electrical / Accessories			1
Seats		n nppcu,wonn,w				Head lights	~		
Carpets	drivers flo	or ripped ,				Tail lights	~		
	A					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	۲		
с <u> </u>						Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Donovan Matara Date: 18 Sep 2018									

I have read and understood this condition guide.

Name: