

Report ID: 18,332,809 Version: 1 Created: 12 Sep 2018

Make:	Holden	Model:	Cruze	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,013	Registration:	HAB425	Reg Expiry:	30 Oct 2018	Engine			I
WoF Expiry:	31 Jul 2019	Odometer:	138,183 Kms	Good No:	18332809	Oil level	~		
VIN:	KL3JA3559DK151955	Next Service:	150000	Service History		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechar	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	S D SC W	-0	P SC		D	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			1n-	EID S	Operation	~		
R = rust PT = paint def				\int	THA	Noise	~		
C = crack					SC	Clutch	•		~
P = pin dent	Ho					CV joints	~		•
* = decals	ssc 916			The	EITPS	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W S P						Performance	~		
			ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
l , ,	pection Comments			indy not be disp	ayea in the diagram		•	oftyre))
Windscreen stonechip CVA					Tyres (lowest observed tread depth of tyres) Left front 2				
							2		mm
						Right front		2	mm
						Left rear	4		mm
Conditions During Body Inspection: Wet									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	indge a onder bor	meenspeede	<u>eominents</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	/ verage					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	omments					Window winder FR	~		
General Comments Heated seat button need attention						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Ti	ming Machanism					Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
	ог сапт вен керіас	ement: N	lo	Kms:		Reversing camera			~
Inspecto	Inspected by: Jason Law Date: 12 Sep 2018								
						Dute. 12 Jep 20			

I have read and understood this condition guide.

Name:

Signature: