

Report ID: 18,332,884 Version: 2 Created: 25 Oct 2018

Make:	Ford	Model:	Mondeo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2014	Registration:	HGM328	Reg Expiry:	24 Jan 2019	Engine			
WoF Expiry:	07 Feb 2019	Odometer:	85,099 Kms	Good No:	18332884	Oil level	~		
VIN:	WF0EXXGBBEDD8625	Next Service:	95000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
					s	Performance	V		
Key:	s w	-0	s s	-0×		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	1		1
B = rust						Operation	~		
PT = paint def	ect NP				70111	Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				74116	CV joints	~		
* = decals	- Alt			10		Wheel bearings	V		
SC = stone chips W = significant scuffs						Brakes			
vv – signincan	W		S S D			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front 5.0 n			mm
						Right front	5.	.0	mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
	_					Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
Canada						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
· ·						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	ming Mechanism	Carelast				Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
Lvidence		ement. N	lo	Kms:		Reversing camera			~
Inspected by: Eddie Marsters Date: 21 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: