

Report ID: 18,333,286 Version: 2 Created: 28 Aug 2018

Make:	Citroen	Model:	C5	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,006	Registration:	ECR56	Reg Expiry:	31 Jan 2019	Engine	1		I
WoF Expiry:		Odometer:	257,500 Kms	Good No:	18333286	Oil level	~		
VIN:	VF7RCRHRJ76725800	Next Service:	256,603kms	Service Histor	y: No	Smoke & fumes	~		
			•			Performance	V		
	port is not a warranty	oration is made	for and milaana	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	SSC S	-0	SP SP	-M-	SD	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect C = crack						Transmission			
						Operation	~		
						Noise	~		
						Clutch	•		~
P = pin dent						CV joints	~		•
*=decals SSC 919						Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs SSC S S S W S									
Noto: como dofacto 8 blamichos may not ha dienlayad in the diagram							~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		- f h ma	
Front bumper loose, lower grille replaced with mesh.						Tyres (lowest observed tread depth of tyres)			
Small crack & moisture in r/h tail light. R/F inner guard broken .						Left front	5.		mm
Some badges missing off boot . One centre cap missing						Right front	5.	0	mm
						Left rear	2.	0	mm
Conditions During Body Inspection: Dry						3 3.0			mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty oil aro	und power steering / A	C pipes.				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Comoto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average				Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		I
Road Conditions During Test Drive: Dry						Central locking	~		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
	•								_
Inspected by: Daryll Timms Date: 21 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: