

Basic Vehicle Condition Guide

Report ID: 18,333,361


Version: 2

Created: 27 Nov 2018

Make: Model: Holden Captiva 7 **Body Style:** SUV Year: 2014 Registration: LNF114 Reg Expiry: 30 Oct 2018 **WoF Expiry: Odometer: Good No:** 13 Sep 2019 76,059 Kms 18333361 VIN: KL3CD2659EB057427 **Next Service:** 85000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy

Interior Comments	2
Seats	Average
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Stuart Melbourne 20 Aug 2018 Inspected by: Date:

N/A
· ·
V
v
V
v
~
~
V
V
V
V
<i>V</i>
\(\tag{ \tag} \tag{ \tag{ \tag{ \tag{ \tag{ \tag{ \tag{ \tag{ \tag{ \ta
es)
mm
mm
mm
mm
V

I have read and understood this condition guide.

Name:

Signature: