

Basic Vehicle Condition Guide

Report ID: 18,333,414

Version:


Created: 20 Aug 2018

Make: Model: Subaru **Body Style:** Hatchback Impreza

Year: 2,008 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 15 Aug 2019 72,246 Kms 18333414 VIN: 7AT0GF09X18016735 **Next Service:** 82,000kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Tidy.

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

Dry

General Comments

Good 2WD hatch.

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Daryll Timms

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	v v			
Performance	~			
Noise	~			
Cooling System		•		
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission		•		
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front	6		mm	
Right front	6		mm	
Left rear	6		mm	
Right rear	6		mm	
Spare	Yes			
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	V V V V V V			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			•	
Reversing camera	1		V	

I have read and understood this condition guide.

Name:

Signature:

20 Aug 2018

Date: