

Basic Vehicle Condition Guide

Report ID: 18,333,609

Pass

~

~

1

1

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition

Created: 20 Aug 2018

Fail

N/A

~

mm

mm

mm

 mm

5

5

5

1


Yes

Make: Model: Subaru **Body Style:** Hatchback Impreza Year: 2,007 Registration: **Reg Expiry: Odometer:** WoF Expiry: **Good No:**

16 Aug 2019 96,553 Kms 18333609 VIN: 7AT0GF09X18003452 **Next Service: Service History:** 106,549kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Dry

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Tidy.

Interior Comment	<u>'S</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Good AWD hatch.

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Daryll Timms

Evidence of Cam Belt Replacement: No

	Dute. 20 Aug 20	,,,	
	Date: 20 Aug 20)18	
i:	Reversing camera		'
	Sat. Nav. (basic test only)		~
	Remote locking	V	
	Central locking	~	
	Number of keys	2	•
	CD (basic test only)	~	
	Radio (basic test only)	~	
	Rear view mirrors	~	
	Window winder RR	~	
	Window winder RL	~	
	Window winder FR	~	
	Window winder FL	~	
	Wipers (front & rear)	V	
		. —	

I have read and understood this condition gu	ide. Naı
--	----------

Name:			