

Basic Vehicle Condition Guide

Report ID: 18,334,191


Version:

Created: 07 Sep 2018

Make: Model: Nissan **Body Style:** Utility Navara Year: 2,012 Registration: Reg Expiry: **GKM922** 02 Sep 2018 WoF Expiry: **Odometer: Good No:** 18334191 06 Aug 2019 269,008 Kms VIN: VSKCVND40A0474494 Next Service: 279000 **Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor stone chips and small crack in the windscreen,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|--------------------------------------|--|--|
| Seats | drivers seat ripped, wear and tear , | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

07 Sep 2018 Inspected by: Donovan Matara Date:

Name:

| | Pass | Fail | N/A | | |
|------------------------------|--|------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | \(\times \) | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | | |
| Clutch | ~ | | | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | | 2 | mm | | |
| Right front | | 3 | mm | | |
| Left rear | 5 | | mm | | |
| Right rear | 5 | | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | V V | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation 🗸 | | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | V V V V V V | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 2 | - | - | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | ~ | | |
| l | | | | | |

Signature: