

Report ID: 18,334,686 Version: 1 Created: 22 Aug 2018

Make:	Mazda	Model:	Capella	Body Style:	Wagon		Pass	Fail	N/A
Year:	1,999	Registration:	ERE126	Reg Expiry:	16 Jul 2019	Engine			
WoF Expiry:	03 Oct 2018	Odometer:	106,075 Kms	Good No:	18334686	Oil level	~		
VIN:	7A8C10R0708106617	Next Service:	not known	Service Histor	r y: No	Smoke & fumes	~		
Note: This report is not a warranty						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
u fui filectiu			nis can be analiged to		enarge.	Coolant condition	~		
Kow	SC W	2	SC SC		SC	Performance	~		
Key: S = scratch		$\overline{(0)}$		5(O)7		Radiator / Hoses (visual)	~		
D = dent					100	Transmission			
R = rust	w Alb					Operation	~		
PT = paint def	ect NP	1				Noise	~		
C = crack					sc	Clutch			~
P = pin dent * = decals	sc dk				~HHS	CV joints	~		
SC = stone chi		10		70	SC SC	Wheel bearings	~		
W = significant scuffs						Brakes			
	W		SC SC	W	R	Performance	~		
Body Ins	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
Stone chips front screen. Door glass rubbers worn out. No cargo blind. Mirrors need painting. Left rear door						Tyres (lowest observed tread depth of tyres)			es)
glass not working from drivers door control						Left front	3		mm
						Right front	4	4	mm
						Left rear		2	mm
Conditions During Body Inspection: Dry						Right rear	3	3	mm
						Spare Yes			
Under Ca	nrriage & Under Bor	net Inspectio	on Comments			Suspension		1	
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		1	
Interior C	ammanta					Operation	~		
Interior Comments Good						Electrical / Accessories		1	
Seats	Good					Head lights	~		
Carpets	Poor					Tail lights	~		
	C					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Poor					Wipers (front & rear)	~		
						Window winder FL	~		
Concert	Commonte					Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2	1	
Road Conditions During Test Drive: Dry						Central locking	~		
	ming Machanism	<i>c</i>	-			Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	′es	Kms: 2(00,490	Reversing camera			~
Inspected by: Brian Hill Date: 22 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: