

Basic Vehicle Condition Guide

Report ID: 18,335,381


Version:

01 Oct 2018 Created:

Make: Model: Mazda **Body Style:** Wagon Atenza Year: 2003 Registration: LPB15 Reg Expiry: 01 Feb 2019 WoF Expiry: **Odometer:** 31 Aug 2019 **Good No:** 18335381 224,097 Kms VIN: 7AT0C139X10110594 **Next Service: Service History:** 234000

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor spider rust on the roof,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	middle console needs a touch up ,		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

01 Oct 2018 Inspected by: Donovan Matara Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\triangle \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	 es)
Left front		2	mm
Right front		 2	mm
Left rear		 5	mm
Right rear	5		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater			<u> </u>
Operation		~	
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	' ·		Π
Remote locking	~		-
Sat. Nav. (basic test only)	-		\ <u>\</u>
Reversing camera			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
eversning curriera			

Signature: