

Report ID: 18,335,979 Version: 1 23 Aug 2018 Created:

Make:	Mini	Model:	ONE	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,002	Registration:	EZG127	Reg Expiry:	24 Aug 2018	Engine			<u> </u>
WoF Expiry:	13 Aug 2019	Odometer:	179,801 Kms	Good No:	18335979	Oil level	~		
VIN:	WMWRA32080TB0473	Next Service:		Service Histor		Smoke & fumes	~		
			-			Performance	~		
	port is not a warranty	anation is maada	for one and miles as	Dauta hava nat	hoon disponsion of	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	S P SC	-161-	S P SC	Radiator / Hoses (visual)	~		
S = scratch	RE	A U			The second se	Transmission	-		
D = dent	ssc 6/6			The	EII S	Operation	~		
R = rust PT = paint def				$\prod$		Noise	~		
C = crack				$+ \vee$	S SC	Clutch	~		
P = pin dent	HID				741L	CV joints	~		
* = decals	SPSC 91			The	ELL SD	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scutts		S P SC		S P SC	Performance	~		
Dedulae		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
BODY INSP	pection Comments				,	Tyres (lowest observed tread	d depth	of tyre	1 2s)
						Left front 7 mm			
						Right front		7	mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		
Conditions During Body Inspection: Dry						Spare	No		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	hood linin	g coming off ,				Dashboard warning lights	~		
	A					Wipers (front & rear)	~		+
Dashboa	rd Average					Window winder FL	~		+
	1					Window winder FR	~		<u> </u>
General C	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		<u> </u>
						Number of keys	2		L
Road Con	ditions During Test	t Drive <sup>.</sup>	Dry		]	Central locking	~		
			Лу			Remote locking	~		<u> </u>
Engine Ti	ming Mechanism:	Unknow	/n			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
						_	1	í	
Inspected by: Donovan Matara Date: 23 Aug 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....