

Report ID: 56,006 Version: 1 Created: 07 Sep 2018

| Make: | Toyota | Model: | Highlander | Body Style: | SUV |][| | Pass | Fail | N/A | |
|---|--------------------------|----------------------|------------------------|--|-------------|----|--|--------|------|-----|--|
| Year: | 2,006 | Registration: | ELM224 | Reg Expiry: | 27 Dec 2018 | | Engine | | | | |
| WoF Expiry: | 10 Sep 2019 | Odometer: | 145,806 Kms | Good No: | 18336314 | | Oil level | ~ | | | |
| VIN: | JTEHP21A600138137 | Next Service: | 154383 | Service Histor | y: No | | Smoke & fumes | V | | | |
| | | | | | | i | Performance | r | | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | | Noise | V | | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | | Cooling System | | | | |
| a full mechan | ical inspection prior to | purchase and t | his can be arranged fo | or an additional of | charge. | ļ | Coolant condition | V | | | |
| | | | | | | ٦ŀ | Performance | V | | | |
| Key: | SC | -0 | | -01- | | | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | | | | | | | Transmission | | | | |
| D = dent R = rust SC S S W | | | | | | | Operation | V | | | |
| PT = paint defe | | FI | | $\left(\left \left(\right) \right\rangle \right)$ | | l | Noise | V | | | |
| C = crack | | | | | | | Clutch | | | ~ | |
| P = pin dent | HIS | | | | 2414 | l | CV joints | ~ | | | |
| * = decals | sc 916 | | | | | | Wheel bearings | ~ | | | |
| SC = stone chips | | | | | | | Brakes | | | | |
| W = significant scuffs SC W | | | | | | | Performance | V | | | |
| | | | | | | | Hand Brake | v | | | |
| Body Inspection Comments | | | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| | | | | | | | | | | mm | |
| | | | | | | l | Right front | | .0 | mm | |
| | | | | | | Jŀ | Left rear | | .0 | mm | |
| Condition | as During Body Ins | noction: | Deri | | | ٦ŀ | Right rear | | .0 | mm | |
| Conditions During Body Inspection: Dry | | | | | |] | Spare Yes | | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | | Suspension | | | | |
| | - | | | | | | Suspension performance | V | | | |
| | | | | | | | Steering performance | v | | | |
| | | | | | | | Shock absorbers | ~ | | | |
| | | | | | | | Air Conditioning / Heater | • | | | |
| | | | | | | | Operation V | | | | |
| Interior Comments | | | | | | lŀ | Electrical / Accessories | • | | | |
| Seats | Good | | | | | | Head lights | V | | | |
| | | | | | | | Tail lights | ~ | | | |
| Carpets | Good | | | | | | Indicators | v v | | | |
| Panels | Good | | | | | | Dashboard warning lights | · · | | | |
| | | | | | | | Wipers (front & rear) | v | | | |
| Dashboa | rd Good | | | | | | Window winder FL | v | | | |
| | | | | | | ļļ | Window winder FR | v | | | |
| General Comments | | | | | | | Window winder RL | v | | | |
| | | | | | | | Window winder RR | v v | | | |
| | | | | | | | Rear view mirrors | v | | | |
| | | | | | | | Radio (basic test only) | v | | | |
| | | | | | | | CD (basic test only) | v | | | |
| | | | | | |] | Number of keys | 1 | L | 1 | |
| Road Conditions During Test Drive: Drv | | | | | | ٦ŀ | Central locking | ~ | | | |
| Road Conditions During Test Drive: Dry | | | | | | ┛┝ | Remote locking | ~ | | | |
| Engine Timing Mechanism: Cambelt | | | | | | 11 | Sat. Nav. (basic test only) | - | | ~ | |
| Evidence of Cam Belt Replacement: No Kms: | | | | | | | Reversing camera | | | ~ | |
| L | • | • | | | | 11 | g cannera | | | - | |
| Inspected by: DM Date: 27 Aug 2018 | | | | | | | | | | | |
| | | | | | | | | | | | |

I have read and understood this condition guide.

Name:

.