

Report ID: 18,336,913 Version: 5 05 Nov 2018 Created:

Make:	Toyota	Model:	Landcruiser	Body Style:	Wagon		Pass	Fail	N/A	
Year:	1994Registration:LBQ66Reg Expiry:10 Jun 2019					Engine				
WoF Expiry:	07 Mar 2019	Odometer:	205,026 Kms	Good No:	18336913	Oil level	~		1	
VIN:	7A8H60H0702081982	Next Service:		Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		-	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechar	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	charge.	Coolant condition	~		1	
						Performance	~		<u> </u>	
Key:	SPT	-0	s s	-01-	S R	Radiator / Hoses (visual)	~		<u> </u>	
S = scratch						Transmission				
D = dent R = rust				715	BIL SD	Operation	~		T	
PT = paint def		F		$\left(\left \left(\right) \right\rangle \right)$		Noise	~			
C = crack					РТ	Clutch			~	
P = pin dent	HID				74114	CV joints	~			
* = decals PT SC 919						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S S S						Performance	~			
Body Inc	portion Commonts	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~			
Body Inspection Comments Driver's door inner handle cover cracked						Tyres (lowest observed tread depth of tyres)				
						Left front 11 mr			mm	
						Right front	-	9	mm	
						Left rear		0	mm	
Conditions During Body Inspection: Dry						Right rear	1	11 mn		
						Spare		Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
Steering performance							~		-	
Shock absorbers							~		<u> </u>	
	Air Conditioning / Heater									
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~		1	
	Average					Tail lights	~			
Carpets						Indicators	~		1	
Panels	Average					Dashboard warning light	5 🖌			
	Average					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL		~		
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Wet						Central locking	~			
						Remote locking			~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
	d hun Dahar 74					Data: 05 N	010			
Inspected by: Bobby Zhong Date: 05 Nov 2018										

I have read and understood this condition guide.

Name:

Signature: