

Basic Vehicle Condition Guide

Report ID: 18,337,959


Version: 1

Created: 31 Aug 2018

Make: Model: Ford Mondeo **Body Style:** Wagon Year: 2,014 Registration: HGR689 Reg Expiry: 23 Aug 2018 WoF Expiry: **Odometer: Good No:** 25 Jul 2019 18337959 118,294 Kms VIN: WF0GXXGBBGDD8604 **Next Service: Service History:** 123000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Dent on left bottom sill panel

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Good		
Panels	Average		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Inspected by: Jason Law Date: 31 Aug 2018

Name:

Kms:

	Pass	Fail	N/A
Engine		1	
Oil level	~		
Smoke & fumes	\(\tau \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	3		mm
Right front	:	3	mm
Left rear	3		mm
Right rear	3		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	<u> </u>		
Remote locking	, , , , , , , , , , , , , , , , , , ,		
Sat. Nav. (basic test only)	_		V
Reversing camera			<i>\'\'</i>
<i>y</i>			

Signature: