

Report ID: 18,338,089 Version: 2 Created: 23 Aug 2018

Make:	Toyota	Model:	Blade	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,007	Registration:		Reg Expiry:		Engine	I	I	L
WoF Expiry:	20 Aug 2019	Odometer:	91,268 Kms	Good No:	18338089	Oil level	~		
VIN:	7AT0H656X18015419	Next Service:	101,265kms	Service Histor		Smoke & fumes	~		
			101/2001015		,	Performance	~		
	port is not a warranty		с I II	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent	GIE			The		Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint defects C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		
* = decals	- MIK			AL-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: con	he defects & blemishes		laved in the diagram	Hand Brake	<i>v</i> <i>v</i>		
Body Insp	pection Comments	10012. 5011		may not be uisp	nayed in the diagraff		-	of +:))
						Tyres (lowest observed tread depth of tyres)			
						Left front		.0	mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear	3.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	103		
OK.						Suspension			
UK.						Suspension performance	~		
						Steering performance	~		
Shock abs							~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats	3000					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		ļ
Coment	ammarta					Window winder FR	~		
General Comments Nice motor car						Window winder RL	~		
NICETHOLOI	Cal					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry							~		
Engine Th	ning Machanian					Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Daryll Timms Date: 22 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: