

Report ID: 18,338,117 Version: 1 Created: 22 Aug 2018

Make: Vol	lkswagen	Model:	Golf	Body Style:	Wagon		Pass	Fail	N/A
Year: 2,0		Registration:		Reg Expiry:		Engine	1		L
2,0	Aug 2019	Odometer:	82,983 Kms	Good No:	18338117	Oil level	~		
	/WZZZ1KZ8M2781(93,000kms	Service Histor		Smoke & fumes	~		+
						Performance	~		<u> </u>
	t is not a warranty		c	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
			nis can be arranged f			Coolant condition	~		
		_				Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch	Se	0			X	Transmission	•		
D = dent	6//6			The		Operation	~		
R = rust	—			10	JHIH	Noise	~		
PT = paint defect C = crack	1			+		Clutch			~
P = pin dent	Ho					CV joints	~		
* = decals	- IAIB				ENR	Wheel bearings			
SC = stone chips	1 Ch	VA		JAL)		Brakes	~		
W = significant scu	uffs	$- \emptyset$		JUF		Performance			1
		Note: com	le defects & blemishe	s may not be disc	laved in the diagram	Hand Brake	レ レ		
Body Inspect	tion Comments	NOLE. SOIT	le délects & biennisne	s may not be disp	layed in the diagram		•	oftura	
						Tyres (lowest observed tread		-	
								5	mm
						Right front		5	mm
[Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
Under Carriage & Under Bonnet Inspection Comments					Spare Yes				
	ige & onder bon	net inspectic	in comments			Suspension	1		
Tidy .						Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
	Good					Electrical / Accessories			T
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboard	Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Tidy turbo wage	on.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditi	ions During Test	Drive:	Dry			Central locking	~		
	-		_			Remote locking	~		
-	ng Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence of C	Cam Belt Replace	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Daryll Timms Date: 22 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: