

Basic Vehicle Condition Guide

Report ID: 18,338,880


Version: 1

Created: 23 Aug 2018

Make: Model: Hilux **Body Style:** Utility Toyota Year: 2,017 Registration: KTD237 Reg Expiry: 14 Nov 2018 **WoF Expiry: Odometer: Good No:** 18338880 15 Aug 2020 15,816 Kms VIN: MR0HA3CD20040017-**Next Service: Service History:** 30000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy

| Interior Comments | | | | |
|-------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

| _ | _ |
|---------|----------|
| Conoral | Comments |
| General | COMMENTS |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

| | Pass | Fail | N/A |
|------------------------------|----------------------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\triangle \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | | |
| Coolant condition | <i>V V</i> | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | V V V V | | |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | • | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 6 | 5 | mm |
| Right front | 6 | | mm |
| Left rear | 6 | | mm |
| Right rear | 6 | 5 | mm |
| Spare | | Yes | |
| Suspension | • | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | V V V V V V | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | \(\triangle \) | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | ~ | | |
| Reversing camera | 1 | | |

Signature:

Inspected by: Stuart Melbourne Date: 23 Aug 2018

Name: