

Report ID: 18,339,855 Version: 1 Created: 31 Aug 2018

Make:	Mazda	Model:	Atenza	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,002	Registration:	FPQ574	Reg Expiry:	22 Nov 2018	Engine			1
WoF Expiry:	13 Oct 2018	Odometer:		Good No:	18339855	Oil level	~		
VIN:	7AT0C139X10100830	Next Service:	219000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
diagnostic tes	sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	V		
Key:	sc s	-0	S P SC S P SC	-M-	S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s c sc			715	SDC	Operation	~		
PT = paint defe				$\left[\left(\right) \right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HID				거네	CV joints	~		
* = decals	ssc 916			-No-	AID	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant	t scuffs S		S P SC P SC		S P SC	Performance	~		
Podula		Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			1 2s)
Front bumper needs alignment ,						Left front 5 mm			
						Right front		5	mm
						Left rear			mm
Conditions During Body Inspection: Wet						Right rear	4 mm 4 mm		
Conditions During Body Inspection: Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension	105		
Slight oil lea	ak,					Suspension performance	~		
-						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	A. 10 40 40 4					Tail lights	v		
Carpets	Average					Indicators	~		+
Panels	Average					Dashboard warning lights	~		+
	A					Wipers (front & rear)	~		+
Dashboa	rd Average					Window winder FL	~		+
	1					Window winder FR	~		+
<u>General C</u>	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		<u> </u>
						Number of keys	1	I	1
Road Con	ditions During Test	t Drive	Wet			Central locking	~		
			wet			Remote locking	~		+
Engine Tir	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							1	1	
Inspected	d by: Donovan Matar	a				Date: 31 Aug 20	18		

I have read and understood this condition guide.

Name:

Signature: