

Report ID: 18,339,903 Version: 1 23 Aug 2018 Created:

Make:	Mitsubishi	Model:	Lancer	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,005	<b>Registration:</b>	DFJ990	Reg Expiry:	20 Oct 2018	Engine	1	I	1
WoF Expiry:	09 Aug 2019	Odometer:	61,459 Kms	Good No:	18339903	Oil level	~		
VIN:	JMFSRCS6A5U005498	Next Service:	72000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	his can be arranged to	r an additional o	narge.	Coolant condition	~		
					S	Performance	V		
Key:		=		500-		Radiator / Hoses (visual)	r		
S = scratch D = dent						Transmission			
R = rust SSC AR						Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack				TT		Clutch			~
P = pin dent	sc de				241 <u>16</u>	CV joints	~		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
	P W		S	W	S D	Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Scratch L sill						Tyres (lowest observed tread depth of tyres)			
						Left front	4		mm
						Right front	:	3	mm
						Left rear		1	mm
Conditions During Body Inspection: Dry						Right rear 3		3	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension		1	
Tidy						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories		1	
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		<b> </b>
	-					Window winder FL	~		
General	Comments					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Cambelt						Remote locking	~		
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
						Reversing camera			~
Inspected by: Stuart Melbourne Date: 23 Aug 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....