

Created:

Report ID: 18,339,988 Version: 1 10 Sep 2018

Signature:

Make:	Ssangyong	Model:	Rexton	Body Style:	SUV		Pass	Fail	N/A
	2,013	Registration:	GSU103	Reg Expiry:	13 Dec 2018	Engine		1	·
	30 Aug 2019	Odometer:	122,992 Kms	Good No:	18339988	Oil level	~		<u> </u>
VIN:	KPTH0C1FSDP317611	Next Service:	133000	Service Histor	y: No	Smoke & fumes	~		<u> </u>
Note: This rer	ort is not a warranty					Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Noise	~		
	ting undertaken. The vical inspection prior to					Cooling System		1	
					indige.	Coolant condition	~		
Kau		\sim	S SC			Performance	~		
Key: S = scratch		$\overline{(0)}$		<u>5(0)</u> -		Radiator / Hoses (visual)	~		
D = dent					A m	Transmission			
R = rust	s sc			-10	HIL IS	Operation	۲		
PT = paint defe	ect NP	1				Noise	۲		
C = crack					SC	Clutch			~
P = pin dent	ssc dl				74Hb	CV joints	~		
* = decals		2 O		10		Wheel bearings	~		
SC = stone chip W = significant	/	Brakes							
		C	D		S D	Performance	~		
Body Insp	ection Comments	Note: son	ne defects & blemis	hes may not be disp	layed in the diagram	Hand Brake	~		
<u></u>						Tyres (lowest observed trea	d depth	of tyre	es)
						Left front	;	7	mm
						Right front	7	7	mm
						Left rear	;	7	mm
Conditions During Body Inspection: Dry						Right rear	;	7	mm
						Spare Yes			
Under Car	rriage & Under Bor	nnet Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		1
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		1
Dashboar	rd					Window winder FL	~		1
						Window winder FR	~		1
General C	omments					Window winder RL	~		1
						Window winder RR	~		1
						Rear view mirrors	~		1
						Radio (basic test only)	~		1
						CD (basic test only)	~		1
						Number of keys	2	1	4
Road Cong	ditions During Test	t Drive:	Dry			Central locking	~		1
						Remote locking	~		<u> </u>
Engine Tin	ning Mechanism:	Unknow	/n			Sat. Nav. (basic test only)			~
Evidence of	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	+		~
1								1	
Inspected	by: Donovan Matar					Date: 10 Sep 20			

I have read and understood this condition guide.

Name: