

Report ID: 18,340,066 Version: 3 Created: 19 Oct 2018

Make:	Volkswagen	Model:	Golf	Body Style:	Wagon		Pass	Fail	N/A
Year:	2007	Registration:	GUY146	Reg Expiry:	26 Apr 2019	Engine			L
WoF Expiry:	13 Mar 2019	Odometer:	105,811 Kms	Good No:	18340066	Oil level	~		
VIN:	WVWZZZ1KZ8M3084(		115000	Service Histor		Smoke & fumes	~		
			115000			Performance	~		
Note: This report is not a warranty						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:	D	-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s dla			1 - L	BIDS	Operation	~		
R = rust				10	7HH	Noise	~		
PT = paint def C = crack	ect III			+		Clutch	V		
P = pin dent	Ho				JIII —				~
* = decals	sc pp			SI_		CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs S W D D W						Brakes			
	5				laura d'in the adia annua	Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<b>6</b> .	Ļ
Left rear taillight cracked						Tyres (lowest observed tread depth of tyres)			
						Left front	e	5	mm
						Right front	6	5	mm
						Left rear	7	7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
<u>Under Ca</u>	image & Under Bor	inet inspectic	on comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	۲		
Dashboa	ira					Window winder FL	~		
	_				 	Window winder FR	~		
General (	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
						L			
Inspected by: John Lindsay Date: 19 Oct 2018									
I have read and understood this condition guide. Name:									