

Report ID: 18,341,238 Version: 1 Created: 24 Aug 2018

Make:	Subaru	Model:	Legacy	Body Style: Hatchback] []	Pass	Fail	N/A
Year:	2,009	Registration:	Leguey	Reg Expiry:	Engine			
WoF Expiry:	,	Odometer:	79,879 Kms	Good No: 18341238	Oil level	~		
VIN:	7AT0GF0BX18011497	Next Service:	89875	Service History: No	Smoke & fumes	~		
			89875		Performance	~		
	<u>port is not a warranty</u>				Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends					-			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.								
					Performance	~		
Key:		-0			Radiator / Hoses (visual)	レ レ		
S = scratch					. , ,	Transmission		
								T
R = rust						~		
PT = paint def	ect				Noise	~		
C = crack P = pin dent	LHC				Clutch			~
* = decals	dig				CV joints	~		
SC = stone chips					Wheel bearings			
W = significant scuffs					Brakes			1
					Performance	~		
Body Ins	pection Comments	Note: son	ne defects & blemishe	es may not be displayed in the diagram	Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)			
					Left front	4.	.0	mm
					Right front	4.	.0	mm
					Left rear	4.	.0	mm
Conditions During Body Inspection: Wet					Right rear	4.0 mm		
					Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension			
					Suspension performance	~		
					Steering performance	~		
	Shock absorbers	~						
					Air Conditioning / Heater			
					Operation 🖌			
Interior Comments					Electrical / Accessories			
Seats	Good				Head lights	~		
Correcto	Good				Tail lights	۲		
Carpets					Indicators	۲		
Panels	Good				Dashboard warning lights	~		
	Good				Wipers (front & rear)	~		
Dashboa	ara				Window winder FL	~		
					Window winder FR	2		
General (<u>Comments</u>				Window winder RL	~		
					Window winder RR	~		
					Rear view mirrors	~		
					Radio (basic test only)	~		
					CD (basic test only)	~		
					Number of keys	1		1
Road Conditions During Test Drive: Wet Central lo						~		
			v#CL		Remote locking	~		1
Engine Ti	ming Mechanism:	Cambel	t		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:	Reversing camera	~		† ·
						1		<u> </u>
Inspected by: Bobby Zhong Date: 24 Aug 2018								

I have read and understood this condition guide.

Name:

Signature: