

Report ID: 18,341,451 Version: 2 13 Sep 2018 Created:

| Make: | Mazda | Model: | Demio | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|--------------------------|-----------------|------------------------|--------------------|--|------------------------------|--------------|---------|-----|
| Year: | 2009 | Registration: | HPB413 | Reg Expiry: | 23 Jan 2019 | Engine | | | |
| WoF Expiry: | 21 Sep 2019 | Odometer: | 173,550 Kms | Good No: | 18341451 | Oil level | ~ | | |
| VIN: | 7AT0C12HX14182431 | Next Service: | 168000 | Service Histor | | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | | 6 | Danta harra nat | la a constituição de la constituição | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | or an additional c | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | V | | |
| Key: | | -0 | | -161- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | sc bla | | | TIS | | Operation | ~ | | |
| R = rust PT = paint def | | | | \prod | | Noise | ~ | | |
| C = crack | | | | + | | Clutch | • | | ~ |
| P = pin dent | -110 | | | | 세비 | CV joints | ~ | | ÷ |
| * = decals | sc 916 | | | - NL | ALL S | Wheel bearings | v | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs W | | | | | | Performance | ~ | | |
| Dealerteen | | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Insp | pection Comments | | | , , | , , | Tyres (lowest observed tread | | of tyre | s) |
| | | | | | Left front 3 mm | | | | |
| | | | | | | Right front | | , 1 | mm |
| | | | | | | Left rear | | | mm |
| Conditions During Rody Inspections | | | | | | Right rear | 2 mm 4 mm | | |
| Conditions During Body Inspection: Dry | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension Yes | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | • | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| | A | | | | | Tail lights | ~ | | |
| Carpets | Average | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | V | | |
| | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Average | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Drv | | | | | | Central locking | ~ | | |
| | | | Dry | | | Remote locking | ~ | | |
| Engine Ti | ming Mechanism: | Timing (| Chain | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ |
| | - | | | | | | | | - |
| Inspected by: Jason Law Date: 13 Sep 2018 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: