

Report ID: 18,341,480 Version: 2 Created: 27 Aug 2018

Make:	Mazda	Model:	Mazda3	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,006	<b>Registration:</b>	DJL506	Reg Expiry:	18 Sep 2018	Engine	I		L
WoF Expiry:	08 Jun 2019	Odometer:	172,404 Kms	Good No:	18341480	Oil level	~		
VIN:	JM0BK103100201139	Next Service:	175843	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	s s		s	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			L
D = dent R = rust	sc			210	HIVS	Operation	~		
PT = paint defe					70111	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIP				74114	CV joints	~		
* = decals	sc 916			10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv – significan						Performance	~		
Body Insr	ection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	3.5 mm		mm
						Right front	3.5 mm		mm
						Left rear	2.	.5	mm
Conditions During Body Inspection: Wet						Right rear	2.5 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	<		
Shock absorbers							~		
						Air Conditioning / Heater			
Operation							~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dastibua	iu .					Window winder FL	~		
	••					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Th	ning Machaniers	<del></del>				Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspector	hv: Xinghui Lin					Date: 26 Aug 20	18		
Inspected by: Xinghui Lin Date: 26 Aug 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....