

Report ID: 18,341,970 Version: 2 06 Nov 2018 Created:

Make:	Toyota	Model:	Hiace	Body Style:	Van		Pass	Fail	N/A
Year:	2011	Registration:	GDR795	Reg Expiry:	12 Sep 2018	Engine	1	l	1
WoF Expiry:	19 Feb 2019	Odometer:	173,222 Kms	Good No:	18341970	Oil level	~		
VIN:	JTFPT22P200008586	Next Service:	177200	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Darte have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	charge.	Coolant condition	~		
		_				Performance	~		
Key:		-0	SC S SC	-161-	S SC	Radiator / Hoses (visual)	v		
S = scratch						Transmission			
						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	•		~
P = pin dent	HIC				세비	CV joints			~
* = decals SC 99						Wheel bearings	~		-
SC = stone chips						Brakes			
W = significant scuffs W D SC SC						Performance	~		
		Note: som		may not be disc		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftvre	es)
Right front door pillar dent Right rear wheel cover missing						Left front 6.5 mm			
Sliding step damage						Right front	0		 mm
CD player fa	aulty					Left rear			mm
Conditions Duving Pody Inspections						Right rear		.5	mm
Conditions During Body Inspection: Dry									
Under Carriage & Under Bonnet Inspection Comments						Suspension Yes			
		•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	v		
						Operation			
Interior Comments						Electrical / Accessories			
Good Good						Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~		
General Comments						Window winder RL	-		~
						Window winder RR			v v
						Rear view mirrors	~		-
						Radio (basic test only)	~		
						CD (basic test only)	-	~	
						Number of keys	1	•	
Dead Conditions During Test Driver						Central locking	· ·		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Yes Kms: 149,620						Reversing camera			v v
									•
Inspected by: Ca Thach Date: 06 Nov 2018									

I have read and understood this condition guide.

Name:

Signature: