

Report ID: 18,342,001 Version: 2 Created: 04 Oct 2018

| Make: | Nissan | Model: | Murano | Body Style: | SUV | | Pass | Fail | N/A |
|---|---|---------------|------------------------|-----------------|--|-----------------------------|------|------------|----------|
| Year: | 2007 | Registration: | KEZ583 | Reg Expiry: | 50V 17 May 2018 | Engine | | | |
| | 2007 21 Dec 2018 | Odometer: | NEZ 383 | Good No: | 17 May 2018 18342001 | Oil level | ~ | | |
| VIN: | 7AT0DH74X16009198 | | 119000 | Service History | | Smoke & fumes | ~ | | |
| | 781001174810009198 | | 119000 | | . 110 | Performance | ~ | | <u> </u> |
| | port is not a warranty | | | | | Noise | ~ | | |
| | a guide only. Conside sting undertaken. The | | | | | Cooling System | V | | |
| | ical inspection prior to | | | | | Coolant condition | ~ | | |
| | | _ | | | | Performance | ~ | | |
| Key: | s sc | -0 | S P SC S P SC | | s | Radiator / Hoses (visual) | ~ | | |
| S = scratch | Se | 20 | | 105 | * | Transmission | V | | |
| D = dent | s sc | | | 1 - L | EID S | | | | |
| R = rust | | | | 10 | | Operation | ~ | | |
| PT = paint def C = crack | ect | - 1 | | + | SC | Noise Clutch | ~ | | |
| C = Crack P = pin dent | Ho | | | | | | | | ~ |
| * = decals | s sc pp | | | SI_ | ELAS | CV joints | ~ | | |
| SC = stone chi | ps US | VA | | 10 | | Wheel bearings | ~ | | |
| W = significant scuffs S SC S S S S S S S S S S S S S S S S S | | | | | | Brakes | | | |
| | | | | | | Performance | ~ | | |
| Body Ins | pection Comments | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | 6 . | Ļ |
| | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| | | | | | | Left front | | 2 | mm |
| | | | | | | Right front | | 2 | mm |
| [| | | | | | Left rear | 6 | 5 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 6 | 5 | mm |
| Under Carriage & Under Bonnet Inspection Comments | | | | | Spare Yes | | | | |
| | inage & onder bor | mermspectic | <u>on comments</u> | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments Average | | | | | | Electrical / Accessories | | | |
| Seats | Avelage | | | | | Head lights | ~ | | |
| Carpets | Average | | | | | Tail lights | ~ | | |
| | A | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| Dashboa | Average | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | liu | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | | ~ | |
| General (| <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | Number of keys | 1 | | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | - | | - | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| Increasted by Denovan Matara | | | | | | | 10 | | |
| Inspected by: Donovan Matara Date: 04 Oct 2018 | | | | | | | | | |
| I have read and understood this condition guide. Name: | | | | | | | | | |