

## **Basic Vehicle Condition Guide**

Report ID: 18,342,306


Version: 2

Created: 30 Aug 2018

Make: Model: Subaru Exiga **Body Style:** Wagon Year: 2,009 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 21 Aug 2019 18342306 110,871 Kms VIN: 7AT0GF1RX18008023 **Next Service: Service History:** 120,866kms

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Tidy.

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

Canaral	Commonts
Generai	Comments

Inspected by:

Nice 2WD 7 seater wagon.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

**Daryll Timms** 

Evidence of Cam Belt Replacement: No

Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\( \triangle \)		
Noise	~		
Cooling System			-
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			-
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	 es)
Left front		 5	mm
Right front		- 5	mm
Left rear	6		mm
Right rear	6		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	\( \triangle \)		
Shock absorbers	~		
Air Conditioning / Heater	ı		
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	V V V V V		
Rear view mirrors	<b>V</b>		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			/

I have read and understood this condition guide.

Name: .....

Signature: .....

30 Aug 2018