

Report ID: 18,342,745 Version: 1 Created: 05 Sep 2018

Make:	Mazda	Model:	Atenza	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,008	<b>Registration:</b>	JQD640	Reg Expiry:	04 May 2019	Engine	1		1
WoF Expiry:	29 Aug 2019	Odometer:	110,730 Kms	Good No:	18342745	Oil level	~		
VIN:	7AT0C139X16101707	Next Service:	120700	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	sc			210	HIVW	Operation	~		
PT = paint def	ect NP				70111	Noise	~		
C = crack						Clutch			~
P = pin dent	sc dl				24116	CV joints	~		
* = decals				10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
<u>body inspection comments</u>						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front	6.0 m		mm
						Right front	3.	.0	mm
						Left rear	3.	.0	mm
Conditions During Body Inspection: Dry						Right rear	3.0 m		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	ning Masharitan	<u> </u>	ci .			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Greg Morgan Date: 28 Aug 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....