

Report ID: 18,342,811 Version: 1 Created: 24 Aug 2018

Signature:

Make:	lsuzu	Model:	Wizard	Body Style:	SUV		Pass	Fail	N/A
Year:	2,000	Registration:	DKE902	Reg Expiry:	31 Aug 2018	Engine	1	I	L
WoF Expiry:	06 Oct 2018	Odometer:	187,339 Kms	Good No:	18342811	Oil level	~		
VIN:	7A8971T0706101770	Next Service:	-	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	iical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SD	-0	SD D	-01-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SSC D S SC						Operation	~		
PT = paint defect						Noise	~		
C = crack					R SC	Clutch			~
P = pin dent	HIS				거네	CV joints		~	-
* = decals SC 99						Wheel bearings	~	-	
SC = stone chips						Brakes			
W = significant scuffs S D D S D						Performance	~		
Dealertee		Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	-	of tyre	es)
Boot stays worn Bonnet wing mirror glass missing									mm
	5 5 5					Right front		5	mm
						Left rear			mm
Conditions During Body Inspection:						Right rear	9		mm
Conditions During Body Inspection: Dry								Yes	
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Windscreen washer bottle cap missing						Suspension performance	~		
Under body oxidisation AC not getting cold						Steering performance		~	
Ac not getting told						Shock absorbers	~	•	
						Air Conditioning / Heater	-		
						Operation		~	
Interior Comments						Electrical / Accessories		-	
Seats	Seats marks on seats					Head lights	~		
	un autor a m					Tail lights	~		
Carpets	marks on	carpets				Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ard Average					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Both front outer cv joint boots broken						Window winder RR	~		
Steering wi	neel not centre					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
			Dry			Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
Inspected by: John Lindsay Date: 24 Aug 2018									

I have read and understood this condition guide.

Name: