

Report ID: 18,343,010 Version: 4 Created: 09 Oct 2018

Make:	Mitsubishi	Model:	Galant	Body Style:	Sedan		Pass	Fail	N/A
Year:	2007	Registration:	JFZ620	Reg Expiry:	26 Oct 2018	Engine			
WoF Expiry:	23 Aug 2019	Odometer:	86,634 Kms	Good No:	18343010	Oil level	~		
VIN:	7AT0CJ0JX15101723	Next Service:	85,300kms	Service Histor	y: No	Smoke & fumes	~		
			•			Performance	~		
	port is not a warranty		for any and miles as	Dauta hava nat	hoon dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	SPW SPW	-161-	S SC W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			The	S PT	Operation	~		
R = rust PT = paint def				\int		Noise	~		
C = crack						Clutch	•		~
P = pin dent					세비	CV joints	~		•
* = decals	scw 916			-NL	ETP sw	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W W S W S D						Performance	~		
		Note: som	ne defects & blemishes	mav not be disc	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments				,	Tyres (lowest observed tread	-	of tyre	(s)
						Left front 6.0 mm			
						Right front		-	mm
						Left rear	6.		mm
	- Dunin a De du la s		_			Right rear	3.	-	mm
Conditions During Body Inspection: Dry						Spare	1.0		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Tidy .						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
Interior Comments						Operation 🖌			
Good									
Seats						Tail lights	v		
Carpets	Average						ン ン		
	Average								
Panels						Dashboard warning lights Wipers (front & rear)	v		
Dashboa	rd scratch.					Window winder FL	ン ン		
						Window winder FL	~		
General C	<u>Comments</u>					Window winder RL	~		
Good Galar						Window winder RL	<i>v</i> <i>v</i>		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	•		
						Number of keys	1		~
Road Conditions During Test Drive: Dry						Central locking	1		
Road Con	aitions During Tes	t Drive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (hain						v
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			v
		N				Reversing camera			~
Inspected by: Daryll Timms Date: 25 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: