

Report ID: 18,343,113 Version: 1 30 Aug 2018 Created:

Make:	Mazda	Model:	Axela	Body Style: Hatch	back		Pass	Fail	N/A
Year:	2,007	Registration:	Алеіа	Reg Expiry:	IDACK	Engine	1 455	i un	
WoF Expiry:		Odometer:	100 506 Kma	Good No: 18343	112	Oil level			
VIN:		Next Service:	109,596 Kms 119,592kms	• • • • • •	_	Smoke & fumes	<b>v</b>		<u> </u>
VIII.	7AT0C13JX18307343	Next Service.	119,592kms	Service History: N	0	Performance	~ ~		<u> </u>
	port is not a warranty						-		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Noise			
						Coolant condition	~		
Key:						Performance	~		
S = scratch	~	(0)		10/		Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust	MIL			T A	V -	Operation	~		
PT = paint def	ect N					Noise	~		
C = crack						Clutch			~
P = pin dent * = decals	dit				₿	CV joints	~		
sC = stone chi		10		70 1		Wheel bearings	~		
W = significant scuffs						Brakes			
J		N		$\sim$		Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishe	s may not be displayed i	n the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	3	8	mm
						Right front	3	}	mm
						Left rear	4	ŀ	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		
					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy .						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		<u> </u>
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~		
General Comments					Window winder RL	~		<u> </u>	
Good tidy hatch .					Window winder RE	~			
						Rear view mirrors	~		<u> </u>
									<u> </u>
						Radio (basic test only)	<b>v</b>		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		<u> </u>
Engine Ti	ming Mechanism	Timina	Chain			Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Lvidence	or cam beit Replac	ement. N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Daryll Timms Date: 30 Aug 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....