

Basic Vehicle Condition Guide

Report ID: 18,343,408


Version:

Created: 21 Nov 2018

Make: Model: Mazda Mazda6 **Body Style:** Sedan Year: 2014 Registration: KCH386 Reg Expiry: 02 Aug 2019 WoF Expiry: **Odometer: Good No:** 03 Feb 2019 86,859 Kms 18343408 VIN: **Next Service:** JM0GJ102100109938 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Aftermarket wheels fitted

Conditions During Body Inspection:

Wet

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Poor | | | |
| Carpets | Poor | | | |
| Panels | Poor | | | |
| Dashboard | Poor | | | |

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Xinghui Lin 21 Nov 2018 Inspected by: Date:

Name:

| | Pass | Fail | N/A | |
|------------------------------|-----------------|-------|----------|--|
| Engine Engine | 1 433 | T GII | 14//1 | |
| Oil level | ·/ | | | |
| Smoke & fumes | • | | | |
| Performance | v | | | |
| Noise | 1/ | | | |
| Cooling System | | | | |
| Coolant condition | v | | | |
| Performance | • | | | |
| Radiator / Hoses (visual) | 1/ | | | |
| Transmission | _ | | | |
| Operation | | | | |
| Noise | • | | | |
| Clutch | · | | | |
| | | | ' | |
| CV joints | - | | | |
| Wheel bearings | <i>'</i> | | | |
| Brakes | | | I | |
| Performance | | | | |
| Hand Brake | | | | |
| Tyres (lowest observed tread | | | | |
| Left front | | | mm | |
| Right front | 4 | | mm | |
| Left rear | 4 | | mm | |
| Right rear | 4 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | <i>\</i> | | | |
| Steering performance | v | | | |
| Shock absorbers | / | | | |
| Air Conditioning / Heater | | | | |
| Operation | - | | | |
| Electrical / Accessories | | 1 | | |
| Head lights | - | | | |
| Tail lights | ~ | | | |
| Indicators | V V V V V V V V | | | |
| Dashboard warning lights | / | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 1 | 1 | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |

Signature: