

## **Basic Vehicle Condition Guide**

Report ID: 18,343,719

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Created: 24 Aug 2018

Fail

N/A

mm

mm

mm

 $\mathsf{mm}$ 

1

1

1

2

Pass

1

~

1

Make: Model: **Body Style: Great Wall** V-Series Utility Year: 2,014 Registration: HRZ737 Reg Expiry: 28 Oct 2018 WoF Expiry: **Odometer: Good No:** 17 May 2019 18343719 70,434 Kms VIN: **Next Service: Service History:** LGWCBE172DC64735 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** No

John Lindsay

I have read and understood this condition guide.

	Remote locking	~				
	Sat. Nav. (basic test only)		~			
Kms:	Reversing camera		~			
Date: 24 Aug 2018						
Name: Signature:						

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.		Cooling System			
		Coolant condition	~		
W S W P		Performance	~		
Key:		Radiator / Hoses (visual)	~		
S = scratch D = dent		Transmission			
R = rust PT = paint defect  R S R SC		Operation	~		
		Noise	~		
C = crack	Clutch	~		Γ	
P = pin dent	CV joints	~		Γ	
- decais		Wheel bearings	~		Γ
SC = stone chips W = significant scuffs	Brakes				
L significant scans	W D W S	Performance	~		
Body Inspection	Comments Note: some defects & blemishes may not be displayed in the diagram	Hand Brake	~		Γ
Right front spotlight	Tyres (lowest observed tread depth of tyres)				
		Left front	6	<u> </u>	n
		Right front	6	 j	n
		Left rear	0	)	n
Conditions During Body Inspection: Dry		Right rear	0	)	n
		Spare		Yes	
<u>Under Carriage &amp; Under Bonnet Inspection Comments</u>		Suspension	•		
Both rear tyres require replacement		Suspension performance	~		
		Steering performance	~		
		Shock absorbers	~		Γ
		Air Conditioning / Heater			
		Operation	~		
<u>Interior Comments</u>		Electrical / Accessories			
Seats	Average	Head lights	~		Г
	Average	Tail lights	~		Γ
Carpets		Indicators	~		Γ
Panels	Average	Dashboard warning lights	~		Γ
Dashboard Good		Wipers (front & rear)	~		
		Window winder FL	~		
		Window winder FR	~		Γ