

Report ID: 18,344,474 Version: 1 30 Aug 2018 Created:

Make:	Mazda	Model:	MPV2300	Body Style:	SUV		Pass	Fail	N/A
Year:	2,004	Registration:	FRT293	Reg Expiry:	10 Aug 2018	Engine			
WoF Expiry:		Odometer:	194,939 Kms	Good No:	18344474	Oil level		~	
VIN:	7AT0C11EX10402651	Next Service:		Service Histor		Smoke & fumes	~	•	
	7/10/11/2020				. 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	SP	-0	S DW			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D=dent							~		1
R = rust				10	7HIH	Operation Noise	~		
PT = paint def C = crack	ect 1			+		Clutch	~		
P = pin dent	HC	KI			JIII —	CV joints			~
* = decals	sc pp			SI_		,	~		
SC = stone chips						Wheel bearings			
W = significant scuffs S S D W D W						Brakes			1
	5 5					Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Headlamps faded, water inside RH headlamp						Tyres (lowest observed tread depth of tyres)			es)
Front and rear bumpers misaligned, insecure Body paint colour difference						Left front	1	3	mm
RH sill body kit insecure. Wiper blades need replacement, rear misaligned						Right front	:	3 r	
FL park light not working. RL sliding door need attention						Left rear		6	
Conditions During Body Inspection: Dry					Right rear	6 m		mm	
					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension	-		
Engine oil le	ow					Suspension performance	~		
						Steering performance		~	
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	. Good					Wipers (front & rear)		~	
Dashboa	ird					Window winder FL	~		
	I					Window winder FR	~		
General Comments					Window winder RL	~			
Steering off centre					Window winder RR	~			
Rattling from rear Audio not turning off, volume control faulty					Rear view mirrors	~			
		,				Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	2	-	I
Road Conditions During Test Driver						Central locking	2 V		
Road Conditions During Test Drive: Dry						Remote locking	-	~	
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)		•	~
-	of Cam Belt Replac		lot Applicable	Kms:		Reversing camera			~
		P							
Inspected by: Mathew Varghese Date: 30 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: