

Basic Vehicle Condition Guide

Report ID: 18,344,488

Version:


Created: 03 Sep 2018

Pass Fail N/A

Make: Model: Holden **Body Style:** Hatchback Barina Year: 2,007 Registration: Reg Expiry: ECG425 16 Sep 2019 **WoF Expiry: Odometer: Good No:** 18344488 14 Sep 2018 180,603 Kms VIN: **Next Service: Service History:** KL3SF486E7B727396 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stonechips on windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Cambelt has been changed but cannot read kms, so should be checked. Coolant additive concentration below manufactures recomended level suggest coolant change.

| <u>Interior Comments</u> | | | |
|--------------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms:

| Engine | | | |
|------------------------------|--|---------|----|
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | V V | | |
| Noise | ~ | | |
| Cooling System | • | • | |
| Coolant condition | \(\times \) | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | ! | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | ~ | | |
| CV joints | \(\times \) | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | depth | of tyre | s) |
| Left front | (| 5 | mm |
| Right front | (| 5 | mm |
| Left rear | 4 | 4 | mm |
| Right rear | 4 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | 1 | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | \(\times \) \(\t | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | 1 | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| | | | |

Reversing camera

Signature:

03 Sep 2018 Inspected by: Roger King

Name:

1