

Report ID: 18,345,206 Version: 1 28 Aug 2018 Created:

Make:	Toyota	Model:	Corolla	Body Style:	Wagon] [Pass	Fail	N/A	
Year:	1,996	Registration:	BYS326	Reg Expiry:	08 Oct 2018	Engine			L	
I	1,990 11 Nov 2018	Odometer:	293,673 Kms	Good No:	18345206	Oil level	~			
VIN:	7A8H6070704004493	Next Service:	unknown	Service Histor		Smoke & fumes	~			
	776110070701001133		unknown			Performance	~			
	port is not a warranty					Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
		_				Performance	~			
Key:	SC W W	-0	S SC W S D SC		S D	Radiator / Hoses (visual)	~			
S = scratch							Transmission			
D = dent						Operation 🖌				
						Noise	~			
PT = paint defect C = crack						Clutch	~			
P = pin dent						CV joints	~			
* = decals PT SC PIP						Wheel bearings				
SC = stone chips						Brakes	~			
W = significant scuffs S D SC W S P P W W D SC W						Performance				
							~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake				
Tail lights cracked .							Tyres (lowest observed tread depth of tyres)			
R/H park light cracked . Rear bumper clips broken .						Left front	2		mm	
Scratched screen						Right front	2		mm	
						Left rear	3		mm	
Conditions During Body Inspection: Dry						Right rear 5 mm			mm	
Under Carriage & Under Report Inspection Comments						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Dirty oil around engine .						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
rips & burn on drivers seat .						Electrical / Accessories				
Seats		i on unvers seat	•			Head lights	~			
Carpets	Average					Tail lights	~			
	Average					Indicators	~			
Panels	Average					Dashboard warning lights	~			
Dashboa	rd Average					Wipers (front & rear)	~			
						Window winder FL	~			
Concert	ammarta					Window winder FR	~			
General Comments OK.						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors			~	
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking			~	
		_	-			Remote locking			2	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 10	3,586	Reversing camera			~	
	Inspected by: Daryll Timms Date: 28 Aug 2018									
Inspected by: Daryll Timms Date: 28 Aug 2018										

I have read and understood this condition guide.

Name:

Signature: