

Report ID: 18,345,460 Version: 1 18 Sep 2018 Created:

Make:	Toyota	Model:	Blade	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	HPJ82	Reg Expiry:	01 May 2019	Engine			
WoF Expiry:	07 Jul 2019	Odometer:	148,560 Kms	Good No:	18345460	Oil level	~		
VIN:	7AT0H656X14032451	Next Service:	148000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	s sc	-0	S P SC S P SC	-01-	s sc	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s c sc			715	SC	Operation	~		
PT = paint defe		F		$\left[\left(\right) \right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	ssc 919			- Jul	S SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S SC S SC S SC S						Performance	~		
Podulas"	action Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		<u> </u>
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
									mm
						Right front	e		mm
						Left rear	6		mm
Conditions During Pody Inspections						Right rear	6		mm
Conditions During Body Inspection: Dry						Spare	<u> </u>		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Danala	Average					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		<u> </u>
	I					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys			L
Pond Conditions During Test Driver D						Central locking	2		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:									v
		N				Reversing camera			~
Inspected by: Donovan Matara Date: 18 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: