

Report ID: 18,345,473 Version: 1 Created: 07 Sep 2018

Make:	Nissan	Model:	Lafesta	Body Style:	SUV		Pass	Fail	N/A
Year:	2,007	Registration:	JNA469	Reg Expiry:	22 Aug 2019	Engine	I	I	L
WoF Expiry:	12 Jan 2019	Odometer:	152,416 Kms	Good No:	18345473	Oil level	~		
VIN:	7AT0DH7DX15114729	Next Service:	152000	Service Histor	V: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	SW	-0	S S	- <u>M</u>	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust S W S W						Operation 🖌			
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74 <u>11</u> 4	CV joints	~		
*=decals						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S S W						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Tailgate struts body mounts sign of rust stain.Scratch left front door mirror.Missing hub cap right front						Tyres (lowest observed tread depth of tyres)			
wheel.Dirty headlight lens.Stone chips front screen.						Left front	6 mm		mm
						Right front	1	5	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD.						Suspension performance	~		
Steering performance							~		
Shock absorbers							~		
						Air Conditioning / Heater	1	1	
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good n lef	t front seat mark	ed.			Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Engine oil le	evel on low mark.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	1	
Road Conditions During Test Drive: Dry Central locking							~		
Remo						Remote locking		~	
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
							10		
Inspected by: Eddie Marsters Date: 07 Sep 2018									

I have read and understood this condition guide.

Name:

Signature: