

Report ID: 18,345,626 Version: 1 Created: 17 Sep 2018

Make:	BMW	Model:	3 Series	Body Style:	Sedan]	Pass	Fail	N/A	
Year:	1999	Registration:	FBN322	Reg Expiry:	16 Oct 2018	Engine				
WoF Expiry:		Odometer:	163,967 Kms	Good No:	18345626	Oil level	~			
VIN:	WBAAL32040FH56972		105,507 1(113	Service Histor		Smoke & fumes	~			
	WBAAL52040111505/2				. 110	Performance	•	~		
	port is not a warranty					Noise	~	•		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
						Performance	~			
Key:		-0				Radiator / Hoses (visual)	v v			
S = scratch	Sec	10			*	Transmission	V			
D=dent S D D D D D D D D D D D D D D D D D D D								 ✓ 		
R = rust				10	7811X	Operation Noise				
PT = paint def C = crack	ect			+		Clutch		~	<u> </u>	
P = pin dent	Ht				االلا				~	
* = decals	SD DE					CV joints	~			
SC = stone chips						Wheel bearings				
W = significant scuffs						Brakes				
						Performance		~		
Body Ins	pection Comments	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		<u> </u>	
Suspension soft					Tyres (lowest observed tread depth of tyres)					
						Left front	5	5.0 m		
						Right front	5	.0	mm	
						Left rear	2	.0	mm	
Conditions During Body Inspection: Wet						Right rear	2.0 mr		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Brakes nois Engine mis						Suspension performance	~			
Engine mis	Sinc					Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	-			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
Coment	Average					Tail lights	~			
Carpets						Indicators	~			
Panels	Average					Dashboard warning lights	~			
	Average					Wipers (front & rear)	~			
Dashboa	ard					Window winder FL	~			
						Window winder FR	~		1	
General Comments						Window winder RL	~		1	
Engine performance poor Oil leaks						Window winder RR	~		1	
Coolant low						Rear view mirrors	~		1	
Intake pipe	split					Radio (basic test only)	~		1	
						CD (basic test only)	~		1	
						Number of keys	2	I	1	
Road Con	ditions During Tes	t Drive	Wot			Central locking	2 V			
			Wet			Remote locking	~		+	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
	·								-	
Inspecte	Inspected by: Jeff Luke Date: 29 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: