

Basic Vehicle Condition Guide

Report ID: 18,346,090


Version:

Created: 29 Aug 2018

Make: Model: Subaru **Body Style:** Hatchback Impreza Year: 2,007 Registration: Reg Expiry: **JAG908** 06 Oct 2018 WoF Expiry: **Odometer: Good No:** 30 Jun 2018 203,866 Kms 18346090 VIN: 7AT0GF09X14002248 **Next Service: Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front bumper misaligned Stone chips on front windscreen LH wing mirror insecure

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Engine oil level low

Interior Comments			
Seats	Poor		
Carpets	Poor		
Panels	Poor		
Dashboard	Poor		

General Comments

Inspected by:

Remote control not working Transmission shudder during test drive the car

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Xinghui Lin

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
Engine	•		
Oil level		~	
Smoke & fumes	~		
Performance	\(\triangle \)		
Noise	~		
Cooling System		•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	•	
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	s)
Left front	4		mm
Right front	4		mm
Left rear	4 mm		mm
Right rear	4		mm
Spare		Yes	
Suspension	•		
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking		~	
Sat. Nav. (basic test only)			1

I have read and understood this condition guide.

Name:

Signature:

29 Aug 2018

1

Reversing camera