

Report ID: 18,346,163 Version: 2 Created: 03 Sep 2018

Make:	Hyundai	Model:	Tucson	Body Style:	SUV		Pass	Fail	N/A
Year:	2,006	Registration: DKD435 Reg Expiry: 15 Jul 2019				Engine			
WoF Expiry:	24 Jan 2019	Odometer:	116,571 Kms	Good No:	18346163	Oil level	~		
VIN:	KMHJN81BR6U286776	Next Service:	119915	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:						Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation	~		
R = rust PT = paint defect C = crack						Noise	~		
						Clutch	•		~
P = pin dent						CV joints	~		
*=decals						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance			
						Hand Brake			
Body Inspection Comments						•			
						Tyres (lowest observed tread depth of tyres)			
						Left front			mm
						Right front		5	mm
						Left rear	6		mm
Conditions During Body Inspection: Dry						Right rear	6.5 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	mermspectic	<u>on comments</u>			Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
		Air Conditioning / Heater							
Interior Comments						Operation	~		
Good						Electrical / Accessories			1
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
	Cood					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
						Window winder FR	~		
General Comments Tailgate glass strut soft.						Window winder RL	~		
l aligate gla	iss strut soft.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
·	dhaa milli ke a								
Inspected by: Eddie Marsters Date: 03 Sep 2018									
I have read and understood this condition guide. Name:									