

Report ID: 18,347,506 Version: 1 Created: 05 Sep 2018

Make:	Mitsubishi	Model:	Nimbus	Body Style:	People Mover		Pass	Fail	N/A
Year:	2,001	Registration:	AGY799	Reg Expiry:	14 Oct 2018	Engine	1		L
WoF Expiry:	,	Odometer:	196,737 Kms	Good No:	18347506	Oil level	~		
VIN:	JMFLRN84W2Z000253	Next Service:	201,000kms	Service Histor		Smoke & fumes	~		
			201,0001113			Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for any and mileage. Parts have not been dismantled or						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	•	~	
Key:	SD S	-0	DSCW DW	-161-	S D	Radiator / Hoses (visual)		~	
S = scratch						Transmission		•	
D = dent	s sc			The	S D PT	Operation	~		
R = rust PT = paint def				í In	THA	Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		
* = decals SC 919 SD						Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs SD W SD SD SD SD SD						Performance	~		
Note: come defecte 8 blamiches may not be displayed in the displayer						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Right front		7	mm
						Left rear	,		mm
						Right rear		7	
Conditions During Body Inspection: Wet						Spare	7 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
Radiator leaking						· ·			
Under body surface rust						Suspension performance Steering performance	v		
	ot grease leakage e mount split					Shock absorbers	v		
	inount spire						~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Average						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Carpets m	issing				Tail lights	~		
Panels	Average			Indicators	~		<u> </u>		
						Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		
General (Comments					Window winder FR	~		
	Johnnents					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	-	
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Remote locking			~
						Sat. Nav. (basic test only)			~
Evidence	ог сант вен керіас	ement: N	lo	Kms:		Reversing camera			~
Inspected by: Ca Thach Date: 05 Sep 2018									
I have read and understood this condition guide. Name:									