

Basic Vehicle Condition Guide

Report ID: 18,347,534


Version: 3

Created: 03 Dec 2018

Make: Model: Mazda CX-5 **Body Style:** SUV Year: 2013 Registration: KGU487 Reg Expiry: 31 Dec 2018 **Odometer:** WoF Expiry: **Good No:** 02 Mar 2019 19,448 Kms 18347534 VIN: **Next Service:** 7AT0C144X16111039 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bobby Zhong Date: 03 Dec 2018

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	V V		
Performance	~		
Noise	~		
Cooling System	•		
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission	•		•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	V		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	4	.5	mm
Right front	4		mm
Left rear	5.5		mm
Right rear	5.5		mm
Spare		N/A	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			1
Operation	~		
Electrical / Accessories		1	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR			
Window winder RL	\(\times \)		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		
L			1

Signature: