

## **Basic Vehicle Condition Guide**

Report ID: 18,489,267

Version: 2


Created: 31 Aug 2018

Make: Model: Mitsubishi **RVR Body Style:** SUV Year: 2,010 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 27 Aug 2019

102,681 Kms 18489267 VIN: 7AT0CJ1KX18010950 **Next Service:** 112,700kms **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Factory repair kit instead of spare wheel.

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Tidy.

| Interior Comments | <u>5</u> |
|-------------------|----------|
| Seats             | Good     |
| Carpets           | Good     |
| Panels            | Good     |
| Dashboard         | Good     |

**General Comments** 

Nice 2WD SUV.

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Kms: Not Applicable

30 Aug 2018 Inspected by: **Daryll Timms** Date:

|                              | Pass                                  | Fail    | N/A  |
|------------------------------|---------------------------------------|---------|------|
| Engine                       | 1 433                                 | T GII   | 14// |
| Oil level                    | ~                                     |         |      |
| Smoke & fumes                | ~                                     |         |      |
| Performance                  | <b>V</b>                              |         |      |
| Noise                        | ~                                     |         |      |
| Cooling System               |                                       |         |      |
| Coolant condition            | ~                                     |         |      |
| Performance                  | ~                                     |         |      |
| Radiator / Hoses (visual)    | ~                                     |         |      |
| Transmission                 |                                       |         | ļ    |
| Operation                    | V                                     |         |      |
| Noise                        | ~                                     |         |      |
| Clutch                       |                                       |         | V    |
| CV joints                    | ~                                     |         | •    |
| Wheel bearings               | ~                                     |         |      |
| Brakes                       |                                       |         |      |
| Performance                  | · /                                   |         |      |
| Hand Brake                   | 1/                                    |         |      |
| Tyres (lowest observed tread | d denth                               | of tyre | 26)  |
| Left front                   | 1                                     |         | mm   |
| Right front                  | 6.0                                   |         | mm   |
| Left rear                    |                                       | 6.0     |      |
|                              | 7.0                                   |         | mm   |
| Right rear                   | 7.0                                   |         | mm   |
| Spare<br>Suspension          |                                       | No      |      |
| Suspension performance       |                                       |         |      |
| Steering performance         |                                       |         |      |
| Shock absorbers              |                                       |         |      |
|                              | <i>V</i>                              |         |      |
| Air Conditioning / Heater    |                                       |         | 1    |
| Operation                    | <b>'</b>                              |         |      |
| Electrical / Accessories     | Ι.                                    | I       | _    |
| Head lights                  | <i>\'</i>                             |         |      |
| Tail lights                  | ~                                     |         |      |
| Indicators                   | ~                                     |         |      |
| Dashboard warning lights     | <b>V</b>                              |         |      |
| Wipers (front & rear)        | -                                     |         |      |
| Window winder FL             | <i>v</i>                              |         |      |
| Window winder FR             | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |         |      |
| Window winder RL             | ~                                     |         |      |
| Window winder RR             | V                                     |         |      |
| Rear view mirrors            | ~                                     |         |      |
| Radio (basic test only)      | ~                                     |         |      |
| CD (basic test only)         | ~                                     |         |      |
| Number of keys               | 2                                     | 1       |      |
| Central locking              | ~                                     |         |      |
| Remote locking               | ~                                     |         |      |
| Sat. Nav. (basic test only)  |                                       |         | ~    |
| Reversing camera             |                                       |         | ~    |
|                              |                                       |         |      |

I have read and understood this condition guide.

| Name |  |  |  |
|------|--|--|--|