

Report ID: 18,489,354 Version: 1 Created: 06 Sep 2018

Make: Volkswagen Model: Polo	Body Style: Hatchback		Pass	Fail	N/A
Year: 2,007 Registration: JZT814	Reg Expiry: 02 Feb 2019	Engine			
WoF Expiry:16 Aug 2019Odometer:125,000 Kms	Good No: 18489354	Oil level	~		
VIN: WVWZZZ9NZ7D03792 Next Service: 119,617kms	Service History: No	Smoke & fumes	~		
		Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and milea	ge Parts have not been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50kn	h/h from cold. The Vendor recommends	Cooling System			
a full mechanical inspection prior to purchase and this can be arranged	l for an additional charge.	Coolant condition	~		
		Performance	~		
Key: SC W SC		Radiator / Hoses (visual)	~		
S = scratch		Transmission	•		
D = dent SC		Operation	~		
R = rust PT = paint defect		Noise	~		
C = crack	SC	Clutch	•		~
P = pin dent		CV joints	~		
*=decals SC 919		Wheel bearings	~		
SC = stone chips		Brakes	v		
W = significant scuffs		Performance	~		
Note: come defects & blamic	nes may not be displayed in the diagram	Hand Brake	v v		
body inspection comments	ies may not be displayed in the diagram	Tyres (lowest observed tread	•	ofture))
Factory fitted tyre repair kit, instead of spare wheel. Reverse camera lens broken .		Left front	•		
			5		mm
		Right front	5		mm
		Left rear	1.	-	mm
Conditions During Body Inspection: Dry		Right rear	3 mm		
Under Carriage & Under Bonnet Inspection Comments		Spare	No		
		Suspension	.		
OK.		Suspension performance	~		
		Steering performance	~		
		Shock absorbers	~		
		Air Conditioning / Heater			
Interior Comments		Operation	~		
Δνεταφ		Electrical / Accessories			
Seats		Head lights	~		
Carpets Average		Tail lights	~		
		Indicators	~		
Panels Average		Dashboard warning lights	~		
Dashboard Average		Wipers (front & rear)	~		
		Window winder FL	~		
		Window winder FR	~		
General Comments		Window winder RL	~		
Nice tidy Cross Polo.		Window winder RR	~		
		Rear view mirrors	~		
		Radio (basic test only)	~		
		CD (basic test only)	~		
		Number of keys	2		
Road Conditions During Test Drive: Dry		Central locking	~		
, ,		Remote locking	~		
Engine Timing Mechanism: Timing Chain		Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable	Kms:	Reversing camera		~	
Inspected by: Daryll Timms		Date: 06 Sep 201			

I have read and understood this condition guide.

Name:

Signature: