

Report ID: 18,489,493 Version: 2 03 Dec 2018 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2008	Registration:	HML755	Reg Expiry:	06 Mar 2019	Engine			L
WoF Expiry:	03 Dec 2019	Odometer:	309,300 Kms	Good No:	18489493	Oil level	~		
VIN:	MR0EZ12G704152153	Next Service:		Service History		Smoke & fumes	~		
			0.0,0.0			Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:	DW		S SP		N SDW	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation 🖌			
						Noise	~		
PT = paint defect C = crack						Clutch			
P = pin dent	Ho						~		
* = decals SC PP						CV joints			~
SC = stone chips						Wheel bearings			
W = significant scuffs S PT P P O PT S D						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Door lock manual key not working/ missing					Tyres (lowest observed tread	d depth	of tyre	es)	
Front bumper misaligned Cupholders need attention					Left front	-	7	mm	
Front windshield moulding need attention						Right front		7 mm	
Stone chip on front windshield						Left rear	6 mm		mm
Conditions During Body Inspection: Dry					Right rear 6		5	mm	
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments Underbody surface rust Dent on LH foot step						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
	Poor					Tail lights	V		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	1					Window winder FR	~		
General Comments					Window winder RL	~			
Clutch weak, squeaking while depressed					Window winder RR	~			
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		L
Road Conditions During Test Drive: Wet						Central locking			
	uning res		Wet			Remote locking	~	-	
Engine Ti	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 300,070						Reversing camera			~
		•							
Inspected by: Bobby Zhong Date: 03 Dec 2018									

I have read and understood this condition guide.

Name:

Signature: