

Report ID: 18,489,752


Version:

Created: 31 Aug 2018

| Make: | BMW | Model: | 3 Series | Body Style: | Sedan |
|-------------|------------------|---------------|-------------|-----------------|-------------|
| Year: | 2,002 | Registration: | AWL200 | Reg Expiry: | 23 Jan 2019 |
| WoF Expiry: | 04 Jul 2019 | Odometer: | 191,916 Kms | Good No: | 18489752 |
| VIN: | WBAAZ72010NG0735 | Next Service: | 206,148kms | Service History | /: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Left rear interior door has stickers on panel.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|---------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Average | | | |
| Dashboard | Good | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Date: 30 Aug 2018 Inspected by: Jason Young

Name:

| | Pass | Fail | N/A |
|--|-----------------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | v v | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | \(\triangle \) | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | | | ~ |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 5 | .5 | mm |
| Right front | 5 | .1 | mm |
| Left rear | 5.9 | | mm |
| Right rear | 6 | .3 | mm |
| Spare | | Yes | |
| Suspension | | | 1 |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | - | | |
| Air Conditioning / Heater | | 1 | |
| Operation | • | | |
| Electrical / Accessories | | Ι | T |
| Head lights | • | | |
| Tail lights | • | | |
| Indicators | | | |
| Dashboard warning lights | V V V V V | | |
| Wipers (front & rear) Window winder FL | | | |
| Window winder FR | • | | |
| Window winder RL | | | |
| Window winder RR | | | |
| Rear view mirrors | | | |
| | V | | |
| Radio (basic test only) | | | |
| CD (basic test only) Number of keys | 2 | | |
| Central locking | 2 | | |
| Remote locking | <i>y</i> | | |
| Sat. Nav. (basic test only) | | | ., |
| Reversing camera | | | 1 |
| neversing carriera | | | |

Signature: